






Assembly Drawing


Tools		Connecting Parts	
		A	52
		B	28
		C	3
		D	1
		E	1
		F	2
		G	60
		H	12
		I	2
		J	6
		K	6
		L	
		M	
		N	
		O	
		P	
		Q	
		R	




Step:1




Step:2




Step:3



Step:4



Step:5



Step:6